




8/25 64RLM


714




Parts



1. x1




2. x1



4/83 13RLM




4/83 11RLM




4/83 22RLM




4/83 24RLM




4/83 23RLM



8/65 319LM




8/65 459LM



1/42 60RLM


10. x1

9. x1




1/45 12RLM

11. x1




12. x1




13. x1


Tools




A




B




C – Glue
D – Silicone




E




$\varnothing 6$ mm
F




G




H




1




2




3




4




5




6







8




I




II



9




10




12


11




I



II




III




13


13




14



15



16



14